

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 34

Township: 7 North


Range: 1 East

Corner ID: Polk M-23

Monument Description & Remarks: 3" diameter Aluminum cap, " T7N R1E, S.33 S.34 1/4, 1983".
Survey Sign 4.5ft above ground at pt. B

References On File:

RECOVERY TIE DRAWING
Field Book 41 Page No. 32



A - 3" Aluminum cap
B - S 86° E 1.01' to Survey
Sign on metal fence post
C - S 86° E 16.75' to MAG
nail in 15" Red Pine
D - S 19° W 43.46' to MAG
nail in 18" Pignut Hickory


Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 27th day of August, 2008.

Kevin Enright

Administered by the Monroe County Surveyor Review Board

Date: 10/7/2008



Index No. X-13
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N R. 1E Mer. N.F. Hoodier County Monroe State Ind.
1/4 Section Corner common to sections 33, 34, and _____


EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1814</u>	Year of search <u>1972</u> By <u>H. Denton</u>
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)	Monument found <u>No</u>

Bearing Trees	
Species <u>B. oak</u>	<u>W. oak</u>
Diameter <u>12"</u>	<u>8"</u>
Bearing <u>N 69 E</u>	<u>N 54 W</u>
Distance <u>11 Ks</u>	<u>8 Ks</u>

Subsequent Corner Restoration	
Year surveyed _____	By _____
Where filed or recorded _____	
Monument _____ (Original, concrete post, iron rod, etc.)	

Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

*
7N R 1E Sec's 33 & 34
X 13
Looking N.W.

Sketch

○ Corner ■ F.S. Land

At time of search:

1. Did you have the record description?
Yes ☒ No _____2. How was search area located?
Pacing, chaining, photos, maps,
etc. photos, maps

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No ☒5. Signature H. Denton

Relation of Evidence to Record Features Along Section Lines

Section line to sections	Object	Record distance	Measured distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Found fence corner in vicinity of 1/4 Sec. Corners. Found a small pile of stones in the fence corner. Fences run N, S, E & W with downed fence & tree line running E. N-S-W fences intersect on west edge of old road

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____